

Appendix B – Best Management Practices (BMPs)

BMP SC08	WASTE HANDLING AND DISPOSAL	
PURPOSE: Prevent or reduce the discharge of pollutants to storm water from waste handling, storage and disposal by through source reduction, re-use, and recycling; and preventing run-on and runoff from waste management areas, including waste/garbage collection areas.		TARGETED ACTIVITIES: ➔ Fuel/Chemical/Oil Waste Storage ➔ . Painting/Stripping ➔ . Waste/Garbage Collection
POLLUTION PREVENTION:		POLLUTANTS of CONCERN:
	Implement the following pollution prevention practices and BMPs to prevent discharges of pollutants from waste handling, storage and disposal to the storm water collection system: <div style="margin-left: 20px;"> <input type="checkbox"/> Inspect on a regular basis waste/garbage collection areas for spills and waste/garbage management containers for leaks. <input type="checkbox"/> Enclose or berm waste/garbage storage areas, if possible, to prevent contact with storm water run-on and run-off. <input type="checkbox"/> Place adequate spill kits in appropriate locations. </div>	➔ Oil and Grease ➔ Paints ➔ . Solvents/Cleaning Solutions ➔ . Trash and Debris ➔ . Vehicle Fluids
OPERATIONS:		APPLICABLE TENANTS/ DEPARTMENTS:
Sub-BMPs - 01 <input type="checkbox"/>	Reduce the amount of waste generated (e.g., use only amount needed, use solvents more than once, practice good inventory control, do not over-buying, purchase long-lasting products, etc.)..	➔ . Aero Mexico ➔ . Alaska Airlines ➔ . Allied Aviation ➔ . American Airlines ➔ . ARFF ➔ . ASIG ➔ . BAX Global ➔ . Delta ➔ . DHL Express ➔ . Elite Line Service ➔ . Exec Air ➔ . FedEx ➔ . HMS Host ➔ . Jet Wash Inc. ➔ . Jimsair ➔ . LPi ➔ . Northwest ➔ . SDCRAA ➔ . Sky West ➔ . Southwest ➔ . SPC ➔ . United ➔ . UPS ➔ . US Airways
- 02 <input type="checkbox"/>	Recycle materials whenever possible.	
- 03 <input type="checkbox"/>	Designate waste/recycling areas with restrict access.	
- 04 <input type="checkbox"/>	Do not locate waste/recycling areas directly in the path of storm drains.	
- 05 <input type="checkbox"/>	Provide secondary containment and cover for wastes.	
- 06 <input type="checkbox"/>	Wastes that are not contained or covered are prevented from contacting storm water and run-on and run-off by the use of berms.	
- 07 <input type="checkbox"/>	All dumpsters are covered and kept closed and any drain holes plugged.	
- 08 <input type="checkbox"/>	Inspect on a frequent basis all waste collection and storage containers for evidence of leaks, spills, compromised structural integrity, and proper closure seal.	
- 09 <input type="checkbox"/>	Train all employees in the proper handling and disposal of waste materials.	
- 10 <input type="checkbox"/>	Store wastes and recyclable materials in appropriate containers and segregate and properly labeled them.	

Appendix B – Best Management Practices (BMPs)

- 11 <input type="checkbox"/> - 12 <input type="checkbox"/> - 13 <input type="checkbox"/> - 14 <input type="checkbox"/>	Wastes are properly characterized and disposed of. Prevent overflow of waste containers by timely pickup/service and removal. Perform dumpster cleaning in designated areas that are bermed to contain wash water. Properly dispose of all fluids collected or discharge to the sanitary sewer. Track waste generated, stored, and disposed.	
STRUCTURAL TREATMENT BMPs: Refer to BMP TC01 for information on structural treatment BMPs.		
AUTHORIZED LOCATIONS FOR WASTE HANDLING AND DISPOSAL:		
<input type="checkbox"/>	Conduct waste handling and disposal activities in the designated areas as shown in the attached map.	
Date:		Version: 1.0

