

## Tenant Summary Sheet

### Tenant:

Frontier

SIC Code: 4512, 4522

Primary Activity: Passenger Carrier

Drainage Area: 7, 12

Nearest MS4 inlet: 200-1000 feet

Contact: Eric Srangsriwong, Manager

E: esrangsriwong@flyfrontier.com , P: 619-683-7765, C: 619-894-1072, F: 619-683-9263

Address: 3707 North Harbor Drive, T2  
San Diego, CA 92101

### Tenant Description and Primary Industrial Activities:

1. Frontier operates out of gate 28 with its main office located near gate 24.
2. Frontier uses their own GSE and personnel to handle baggage.
3. GAT performs GSE maintenance at the gate or GAT shop.
4. GAT handles cargo and cleans GSE.
5. Pacific Aircraft Maintenance minor aircraft maintenance while parked on ramp.
6. One flammables cabinet is located at gate 24 containing engine oil and paint. Currently tenant is looking to remove all Hazardous Materials from operational area.
7. GSE equipment is a combination of gas and propane.
8. Drip pans are used on an as-needed basis.
9. Sweeping is done on an as-needed basis.
10. Tenant uses the Airport Storm Water Management Plan, and does not have a Hazardous Materials Business Plan.

### Significant Materials Potentially Exposed to Storm Water:

#### Potential Pollutant Sources

Aircraft fueling  
Aircraft maintenance  
Aircraft sanitary services  
Cargo handling  
Equipment fueling  
Equipment maintenance  
Equipment storage  
Fluid leaks from aircraft  
Fuel spills  
Fuel storage  
Potable water flushing  
Vehicle fueling  
Vehicle maintenance  
Vehicle parking

#### Potential Pollutants

Hydraulic fluids, Fuel, Trash, Cleaning solutions, Lavatory chemicals, Lavatory wastes, Oil and Grease, Lubricants, Paints

### Best Management Practices and Current Structural Controls:

The list below identifies the BMP categories and specific BMPs that are applicable to Frontier. Appendix B provides a description of each BMP category.

#### Applicable BMP Categories

Non-Storm Water Management  
Outdoor Equipment Ops and Maintenance Areas  
Aircraft, Ground Vehicle and Equipment Maintenance  
Aircraft, Ground Vehicle and Equipment Fueling

#### BMP Number

SC01 - 1, 2, 4  
SC02A - 2, 1  
SC02B - 10, 3, 7, 9, 1, 11, 13, 2, 4, 5, 6, 8  
SC03 - 1, 2, 4, 5, 6, 8

## Tenant Summary Sheet

Tenant:

Frontier

Applicable BMP Categories

Aircraft, Ground Vehicle and Equipment Fueling

Outdoor Loading/Unloading of Materials

Outdoor/Indoor Material Storage

Waste Handling and Disposal

Employee Training

Lavatory Service Operation

Housekeeping

Safer/Alternative Products

Spill Prevention, Control, and Clean-up

BMP Number

SC03 - 5, 4, 2, 6

SC06 - 1, 2, 6

SC07 - 1, 2, 3, 7

SC08 - 7, 1, 10, 12, 2, 3, 4, 8, 9

SC10 - 4, 1, 2, 3

SC11 - 4, 10, 3, 5, 6, 7, 8, 9

SC18 - 4, 1, 2, 3, 5, 6, 7, 8, 9

SC19 - 1, 2

SR01 - 2, 1, 3, 4, 5, 6, 7, 8, 9

Structural control measures used at Frontier:



PROJECT NO.:  
5013-11-0003

DATE:  
November 2011

DRAWN BY:  
RMH

CHECKED BY:  
AA



**MACTEC**

MACTEC Engineering and Consulting, Inc.

**Frontier  
Operating Areas**  
San Diego International Airport

FIGURE

**E-15**