

Alaska Airlines

SIC Codes	4512, 4522	Contact Information	
Primary Activity	Passenger Carrier	Warren Paulsen	Supervisor - Maintenance
Drainage Areas	07, 08	P 6196804651	C 9495474896
Nearest MS4 Inlet	< 200 ft.	warren.paulsen@alaskaair.com	
Address	3665 North Harbor Dr. #228 San Diego, CA 92101	Janet Baad P 2063927947 janet.baad@alaskaair.com	Environmental Contact C 2067944975

Facility Description and Activities

1. DAL Global Services is a vendor to Alaska, and provides ground handling services and maintains their own vehicles. GES maintains all Alaska owned equipment and vehicles. Maintenance operations and materials for DAL have moved to the cargo area maintenance shop.
2. Alaska performs minor aircraft maintenance at the gate. Materials are stored indoors in the maintenance office, except for three large storage sheds outside. All three storage sheds have hazardous materials and all liquid has secondary containment.
3. There are two clam shell containers stored outdoors, each containing two barrels of hazardous liquids.
4. GAT is contracted to perform cargo handling.
5. GES maintains Alaska equipment, trucks, AC carts, etc.
6. Aircraft parts and materials are stored indoors in the Material Storage Area by Gate 16. All other significant materials are stored outdoors and contained in 3 covered sheds.
7. Wastes are stored in the Waste Accumulation.
8. Spill response material for fuel and lavatory spills is kept in a cart between Gate 16 and 17.
9. Operate out of gates 13 through 18. Aircraft Remain Over Night (RON) at gates 20 and 21 and aircraft is kept at Commuter Terminal 1 every night.
10. Aircrafts are dry washed only.
11. Contact Janet Baad for HAZMAT Business Plan.
12. Alaska and Virgin are merging and will be under one Single Operating System (SOS) as of January 2018.

Significant Materials/Activities Potentially Exposed to Storm Water

Potential Pollutant Sources

Aircraft sanitary services
Cargo handling
Equipment storage
Fluid leaks
Fuel spills, Fuel transfer
Material loading/unloading
Outdoor waste storage
Potable water flushing
Tank fuel transfer
Trash collection

Potential Pollutants

Adhesives
Battery Acid
Cleaning Solutions
Degreasers
Fuel
Fuel (Sump)
Hydraulic Fluids
Lavatory Chemical Wastes
Lavatory Chemicals
Lavatory Wastes
Lubricants
Oil & Grease
Recyclables
Sealants
Trash

Individual Tenant Summary From Appendix E

Best Management Practices Applicable to Facility


Activities

Non-Storm Water Management
Outdoor Equipment Ops Maintenance Areas
Aircraft, Ground Vehicle & Equipment Maintenance
Electric Vehicle Maintenance
Aircraft, Ground Vehicle & Equipment Fueling
Aircraft, Ground Vehicle & Equipment Cleaning
Outdoor Loading/Unloading of Materials
Outdoor Material Storage
Waste Handling & Disposal
Employee Training
Lavatory Service Operation
Potable Water System Flushing
Housekeeping
Safer/Alternative Products
Spill Prevention, Control & Clean Up

BMPs

SC01 - 1, 2, 4, 7
SC02A - 1, 2
SC02B - 1, 2, 3, 4, 5, 6, 7, 8, 9, 10, 11, 12, 13
SC02C - 1, 2, 3, 4, 5, 6, 7, 8, 9
SC03 - 1, 2, 4, 5, 6, 8
SC04 - 1, 2, 5
SC06 - 1, 2, 3, 4, 6, 7
SC07 - 1, 2, 3, 7, 11, 12
SC08 - 1, 2, 3, 4, 5, 8, 9, 10, 11, 12, 14
SC10 - 1, 2, 3, 4
SC11 - 3, 4, 5, 6, 7, 8, 9, 10, 11
SC14 - 1, 2
SC18 - 1, 2, 3, 4, 5, 6, 7, 8, 9
SC19 - 1, 2
SR01 - 1, 2, 3, 4, 5, 6, 7, 8, 9

* Appendix B provides descriptions for each BMP category.



Aerial Image Source:
Aerotech Mapping Inc.
ATM # C0116-008
Aerial Flight Date: 8/22/2016

PROJECT NO.:
5025-18-2002
DATE:
JANUARY 2019
DRAWN BY:
CAB
CHECKED BY:
AA/NP

wood.

SAN DIEGO INTERNATIONAL AIRPORT

**Alaska
Operating Areas**

FIGURE

E-3

Intentionally Left Blank