

Allegiant Air

SIC Codes 4512, 4522
 Primary Activity Passenger Carrier
 Drainage Areas 12
 Nearest MS4 Inlet 200 - 1000 ft.
 Address 3707 North Harbor Dr. T2E
 San Diego, CA 92101

Contact Information
 Ken Sturgill General Manager
 P 6192200164 C 7757710699
 ksturgill@atsstl.com

 Charles Hopkins Manager - Regional
 P 7028305760 C 5153069605
 charles.hopkins@allegiantair.com

Facility Description and Activities

1. All equipment maintenance is done by GES. Daily vital fluid checks are performed by ATS staff and monthly Preventive Maintenance Inspections are conducted by Tom Mascarenas of GES. ATS is a subtenant to Allegiant.
2. Fueling is conducted by ASIG at the Gates. ATS conducts monthly station safety audits which include observing fueling. ATS requests a poundage of fuel to be put into the aircraft prior to each fueling.
3. Cleaning of vehicles is done at the triturator facility. No aircraft cleaning is performed at SIDA.
4. All aircraft maintenance is performed by Pacific Aircraft Maintenance.
5. Tenant operates primarily out of Gate 23 (gate 22 is a shared gate also used by Hawaiian and West Jet). Allegiant has flights twice per week (Thursday & Sunday) from February to August.
6. No potable water flushing occurs at the airport, all flushing and cleaning is done offsite.
7. ATS is a subtenant of Allegiant and performs services above the wing and below the wing for Allegiant.

Significant Materials/Activities Potentially Exposed to Storm Water

Potential Pollutant Sources

Aircraft sanitary services
 Equipment storage
 Fluid leaks
 Fuel spills, Fuel transfer
 Fuel storage
 Material loading/unloading
 Outdoor waste storage
 Trash collection

Potential Pollutants

Anti Freeze
 Battery Acid
 Cleaning Solutions
 Fuel
 Lavatory Chemicals
 Lavatory Wastes
 Lubricants
 Metals
 Oil & Grease
 Sediment

Trash

Best Management Practices Applicable to Facility

Activities

Non-Storm Water Management
 Outdoor Equipment Ops Maintenance Areas
 Aircraft, Ground Vehicle & Equipment Maintenance
 Aircraft, Ground Vehicle & Equipment Fueling
 Aircraft, Ground Vehicle & Equipment Cleaning
 Outdoor Loading/Unloading of Materials
 Waste Handling & Disposal
 Employee Training
 Lavatory Service Operation
 Housekeeping
 Safer/Alternative Products
 Spill Prevention, Control & Clean Up

BMPs

SC01 - 1, 2, 4
 SC02A - 1, 2
 SC02B - 1, 2, 3, 4, 5, 6, 7, 8, 10, 11, 12, 13
 SC03 - 1, 2, 3, 4, 5, 6, 8
 SC04 - 1, 2
 SC06 - 1, 2, 3, 6, 7
 SC08 - 1, 2, 3, 4, 5, 8, 9, 12
 SC10 - 1, 2, 3, 4
 SC11 - 3, 4, 5, 6, 7, 8, 9, 10
 SC18 - 1, 2, 3, 4, 5, 9
 SC19 - 1, 2
 SR01 - 1, 2, 3, 5, 6, 7, 8, 9

* Appendix B provides descriptions for each BMP category.

Structural Control measures used by facility:

Materials Storage Area

Operates out of gate 23; no significant material storage

Materials Storage Amounts

No materials recorded above 55gallons

Shipping/Receiving Area

Not recorded



PROJECT NO.:
5025-13-0031

DATE:
JUNE 2015

DRAWN BY:
RMH

CHECKED BY:
AJA



**Allegiant
Operating Areas
San Diego International Airport**

FIGURE
E-6

Intentionally Left Blank