

Envoy

SIC Codes 4512, 4522
 Primary Activity Passenger Carrier
 Drainage Areas 6
 Nearest MS4 Inlet < 200 ft.
 Address 3225 North Harbor Dr. #109
 San Diego, CA 92101

Contact Information
 Sheryl Tuailena Supervisor
 P 6192317203
 sheryl.tuailena@aa.com

 Hellen Tran Compliance Coordinator
 P 6192317205
 hellen.tran@aa.com

Facility Description and Activities

*Sky West does not hold lease space at the San Diego airport; however, their aircrafts still land at the San Diego Airport. Envoy currently holds the ground handling contract, and any storm water concerns associated with Sky West's ground operations should be assigned to Envoy. **Effective July, 2015, Envoy will be relocated to American's gates in Terminal 2.

1. American Eagle is now know as Envoy and is owned wholly by American Airlines. Envoy will provide commuter/express flights for multiple airlines. Planes will remain branded as the company that they belong to.
2. GAT performs vehicle and equipment maintenance at the GAT shop. Painting is conducted offsite.
3. ASIG is contracted to perform all fueling activities.
4. Minor aircraft maintenance is performed by Pacific Aircraft Maintenance on the ramp. Major maintenance is done in LA.
5. Aircraft or vehicles are washed offsite the airport.
6. American Airlines stores and arranges disposal of American Eagle's waste oils.
7. Honeybee cleaner is stored on spill pallet inside baggage loading area. No other significant materials are stored onsite.
8. American Eagle owns two lavatory carts. Lavatory activities are performed on request only by the tenant and the lavatory waste is disposed of at the triturator facility.
9. ELS is contracted to perform belt maintenance.
10. The tenant utilizes American Airlines Environmental Business Plan.
11. The tenant uses parking places 2, 4 and 6 on the Commuter Terminal.
12. Most of tenant's GSE is electric.
13. Sky West flies airplanes into the airport, but does not have any property at the airport.

Significant Materials/Activities Potentially Exposed to Storm Water

Potential Pollutant Sources

Potential Pollutants

Aircraft sanitary services
 Equipment storage
 Fluid leaks
 Fuel spills, Fuel transfer
 Outdoor waste storage
 Trash collection

Tenant Summaries

Anti Freeze
 Battery Acid
 Cleaning Solutions
 Fuel
 Lavatory Chemicals
 Lavatory Wastes
 Lubricants
 Oil & Grease
 Sediment
 Trash

Best Management Practices Applicable to Facility

Activities

Non-Storm Water Management
 Outdoor Equipment Ops Maintenance Areas
 Aircraft, Ground Vehicle & Equipment Maintenance
 Aircraft, Ground Vehicle & Equipment Fueling
 Aircraft, Ground Vehicle & Equipment Cleaning
 Outdoor Material Storage
 Waste Handling & Disposal
 Employee Training
 Lavatory Service Operation
 Housekeeping
 Safer/Alternative Products
 Spill Prevention, Control & Clean Up

BMPs

SC01 - 1, 2, 4
 SC02A - 1, 2
 SC02B - 1, 2, 3, 4, 5, 6, 10, 11, 12, 13
 SC03 - 1, 2, 4, 5, 6, 8, 9
 SC04 - 1, 2
 SC07 - 11, 12
 SC08 - 1, 2, 3, 4, 5, 8, 9, 10, 11, 12
 SC10 - 1, 2, 3, 4
 SC11 - 3, 4, 5, 6, 7, 8, 9, 10
 SC18 - 1, 2, 3, 4, 5, 6, 7, 8, 9
 SC19 - 1, 2
 SR01 - 1, 2, 3, 4, 5, 6, 7, 8, 9

* Appendix B provides descriptions for each BMP category.

Structural Control measures used by facility:

Materials Storage Area

American Airlines maintenance shop

Materials Storage Amounts

Waste oils stored at American Airlines maintenance shop may be over 55 gallon

Honeybee cleaner stored on spill pallet inside commuter terminal baggage loading area (as of Fall 2014; Spring 2015 commuter terminal has closed)

Shipping/Receiving Area

American Airlines maintenance shop

Intentionally Left Blank



PROJECT NO.:
5025-13-0031

DATE:
JUNE 2015

DRAWN BY:
RMH

CHECKED BY:
AJA

amec foster wheeler



**American/Envoy
Operating Areas**

San Diego International Airport

FIGURE

E-8

Intentionally Left Blank